



901 West 94th Street
 Minneapolis MN 55420-4236



Minnesota 800-352-2812
 Iowa 800-342-7002
 Missouri 800-342-7002
 Wisconsin 800-342-7002

Service Invoice

Invoice SI000290419
Date 2/8/2023
Call Number SC00313180
Location New Hampton
Page 1 / 3

Sold to: MACHINE INVENTORY ADD TO BV - AGRI
 ATTN: CORP MACHINE INVENTORY ACCOUNTANT
 901 W 94TH ST
 MINNEAPOLIS, MN 55420-4236

Ship to 1819 MCCLOUD AVE
 NEW HAMPTON, IA 50659-9303

Invoice Account	Payment	Due Date
I002845	Internal - No Payment	2/8/2023

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		S77	AGCRS7700BHTV7714	EQ0081149	1,903

SC00313180-003 Remove & Install - V-Belt(S)

Customer complaint: Needs new V Belts

Quantity	Type	Part Number	Description	Unit Price	Amount
1.00	Parts	71368809 - 200	DRIVE BELT	109.54	109.54
1.00	Parts	71464666 - 200	DRIVE BELT-BIN UNLOA	168.72	168.72
1.00	Parts	71396754 - 200	V-BELT	26.90	26.90
2.00	Parts	4526011 - 504	GREASE-MULTI	2.88	5.76
1.00	Parts	71432846 - 200	DRIVE BELT	239.33	239.33
1.00	Parts	71453906 - 200	BELT	673.54	673.54
	Labor		Labor		1,406.00

Credit card payments are only accepted at Point of Sale
 A service charge of 1 1/2% per month will be assessed on all past due accounts.

MACHINE INVENTORY ADD TO BV - AGRI
 ATTN: CORP MACHINE INVENTORY
 ACCOUNTANT
 901 W 94TH ST
 MINNEAPOLIS, MN 55420-4236

Invoice SI000290419
Date 2/8/2023
Account I002845

Please Remit to:

Ziegler Inc.
 SDS 12-0436
 PO BOX 86
 MINNEAPOLIS, MN 55486-0436

Amount Due:

\$7,450.25

Amount Enclosed:

	\$7,450.25

Parts: 1,223.79 Labor: 1,406.00 Segment Subtotal: 2,629.79

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		S77	AGCRS7700BHTV7714	EQ0081149	1,903

SC00313180-004 Install - Wheel & Tire

Repair process comments: BROUGHT COMBINE IN THE SHOP, JACKED UP THE LEFT FRONT TIRE, INSTALLED THE LEFT DUEL. LET COMBINE DOWN. MOVED THE JACK TO THE RIGHT SIDE OF COMBINE, JACKED IT UP, INSTALLED THE RIGHT DUEL. LET COMBINE DOWN. DROVE COMBINE OUT OF THE SHOP.

Quantity	Type	Part Number	Description	Unit Price	Amount
	Labor		Labor		962.00

Labor: 962.00 Segment Subtotal: 962.00

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		S77	AGCRS7700BHTV7714	EQ0081149	1,903

SC00313180-001 PMI - Machine

Customer complaint: Yearly check over

Repair process comments: Checked fluids in transmission, final drives, cylinder gearbox, engine and radiator. Checked machine over. Replaced fan drive belt, rotary screen belt and clean grain elevator drive belt. Chopper knives need to be replaced. Header variable drive piston leaks. Field lights don't work.

Quantity	Type	Part Number	Description	Unit Price	Amount
1.00	Misc		Labor		

Labor: 475.00 Misc: 100.00 Segment Subtotal: 575.00

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		S77	AGCRS7700BHTV7714	EQ0081149	1,903

SC00313180-002 Remove & Install - Battery

Customer complaint: Engine does not turn over

Repair process comments: Removed and replaced batteries

Quantity	Type	Part Number	Description	Unit Price	Amount
3.00	Parts	79018975 - 200	BATTERY-GRP 31	148.65	445.95
	Labor		Labor		148.00

Parts: 445.95 Labor: 148.00 Segment Subtotal: 593.95

Invoice SI000290419	Date 2/8/2023	Call Number SC00313180	Location New Hampton	Page 3 / 3
-------------------------------	-------------------------	----------------------------------	--------------------------------	----------------------

Customer PO	Customer EQ	Model S77	Serial Number AGCRS7700BHTV7714	Equipment ID EQ0081149	Segment SMU 1,903
--------------------	--------------------	---------------------	---	----------------------------------	-----------------------------

SC00313180-008 Repair - Pulley(S)

Customer complaint: Inspection repair.
 Repair process comments: Loosened main drive idler and unload drive. Removed main idler arm. Put new bushings and sleeve in the arm. Put on a new idler pulley. Replaced the main drive belt.
 Reinstalled the idler. Put unload belt on. Put on a new brush holder. Retightened both idlers. Checked for alignment. Test run.

Quantity	Type	Part Number	Description	Unit Price	Amount
2.00	Parts	75W90-QT - 210	75W90 SYN	8.77	17.54
1.00	Parts	ACW2077160 - 200	MAIN DRIVE BELT	374.38	374.38
1.00	Parts	71314321 - 200	BRUSH HOLDER	180.82	180.82
1.00	Parts	2606620W1 - 200	SLEEVE-42430	34.59	34.59
2.00	Parts	1689170W1 - 200	BUSHING-1" X 1-1/4"	23.59	47.18
1.00	Parts	71309767 - 200	IDLER PULLEY-8" DIA	95.00	95.00
	Labor		Labor		1,665.00

Parts: 749.51 Labor: 1,665.00 Segment Subtotal: 2,414.51

Subtotal	7,175.25
Shop Supplies and Environmental Fees	275.00
Sales Tax	0.00
Total	\$ 7,450.25